Gulf Offshore N.S. Ltd DROPS Forum 29th Feb 2012








DESPITE OUR BEST EFFORTS DROPPED OBJECTS & POTENTIAL DROPPED OBJECTS CONTINUE TO BE A MAJOR PROBLEM IN THE OFFSHORE INDUSTRY

FOR EVERY DROPPED OBJECT THAT IS REPORTED, 2 MORE GO UNREPORTED

SO, WHAT'S THE PROBLEM WITH NOT REPORTING DROPPED OBJECTS OR FOLLOWING UP?


IF IT GOES UNREPORTED OR IS NOT FOLLOWED UP, THEN THE PROBLEM OR ROOT CAUSE CANNOT BE ADDRESSED & THE LIKELIHOOD OF A REOCCURRENCE INCREASES SIGNIFICANTLY





GULFMARK








Dropped Objects Break down 2011 & 2012 YTD

Offshore Base Vessel Other








Dropped Objects Breakdown

Checks Failed Unsecured Doors Maintenance Management








Type of Offshore Installation

Semi Sub Platform Jackup FPSO







THE GREATER THE DISTANCE AN OBJECT FALLS THROUGH, THE MORE TIME IT HAS TO ACCELERATE

THE IMPACT CAUSED BY THIS ACCELERATION CAN BE DEVASTATING

AN OBJECT FALLING FROM 10m OR 30 feet HAS AN IMACT EQUIVIVALENT TO

10 TIMES ITS OWN WEIGHT

LETS PUT THIS INTO PERSPECTIVE



THIS SHACKLE



ABAS

ND SHOKING ON DECK

THE R.

Sin 1

ABAS

王明

CIL

LA

H

FIND

TO THIS POINT

Status -

HAS ROUGHLY THE IMPACT FORCE EQUIVALENT TO THE WEIGHT OF THIS SHACKLE















PLAN INTRODUCED WITH IMMEDIATE EFFECT IN 2011 TO ELIMINATE THE PROBLEM OF CORROSION DEBRIS ON THE UNDERSIDE OF CONTAINERS

ALL CONTAINERS WILL UNDERTAKE A FULL UNDERSIDE CORROSION CHECK

ALL CONTAINERS WILL BE PLACED ON TRESTLES WITH ANY HEAVY CORROSION BEING REMOVED BY HAMMERING & HIGH PRESSURE JET WASHING

ANY UNITS FOUND TO BE HEAVILY CORRODED WILL BE TAKEN OUT OF SERVICE AND REPLACED

REFURB PROGRAM IN PLACE WITH A NUMBER OF UNITS BEING SWAPPED OUT EACH MONTH









1.5m/5 foot METAL ANGLE IRON FROM GRATING OF A TANK UNIT


Atmospheric corrosion, poor design / manufacture and the high impact lifting operations of these containers have caused the relatively small spot welds to deteriorate and crack over a period of time. These three damage mechanisms have ultimately resulted in the angle iron detaching from the container during the routine lifting operation.

A visual inspection of all the other containers of the same design onboard the platform that could be accessed safely was carried out. List as follows of the containers found with the same cracking to the spot welds: CT421, CT267, CT365, CT402, CT193, CT385, CT149, CT288, CT209, CT137

















To raise awareness of Dropped Objects and their consequences.

To assist with identifying and assessing potential Dropped Objects while planning and monitoring tasks

To assist with identifying controls for prevention and mitigation of potential Dropped Objects



GULF/TAQA Quarterly Meeting HSE Statistics

LOOSE OBJECTS LIFE THREATENING. YOU CAN AVOID IT!



SNS DOOL THERE IS ALWAYS TIME TO DO IT RIGHT - DO IT SAFELY OR NOT AT ALL NOGEPA





SISPOOL THERE IS ALWAYS TIME TO DO IT RIGHT - DO IT SAFELY OR NOT AT ALL NOGEPA



SNS pool There is always time to do it right - Do it safely or not at all NOGEPA



GULF/TAQA Quarterly Meeting HSE Statistics

BANKSMAN CHECK TAGS

DROPPED OBJECT & PRE LOADING CHECKS HANDBOOKS

PHYSICAL CHECK OF DOORS

REMOVAL FROM SERVICE OF CONTAINERS WITH POOR DESIGN ROUND DOOR HANDLES AND LOCKING DEVICES/MODIFICATION OF EXISTING CONTAINERS

EDUCATE CONTRACTORS WORKING ONBOARD SHIPS







This number operates 24 hours a day.

f disconnection

uired, diving or topside.

19 number will be advised they have reached

• The medics should call +44 (0)20 8762 8379
















GULFMARK 0 F F S H 0 R E

B-OECK



PRE LOADING/BACKLOADING CHECKS FAILING

MAINTENANCE MANAGEMENT OF OLDER CARGO UNITS

AWARENESS

CONSEQUENCES



