

MSF – Dropped Objects

01/12/2015


GULFMARK OFFSHORE

GulfMark Offshore, Inc.



Marine Safety Forum






DROPPED OBJECTS




Potential / Dropped Objects Summary







Potential / Dropped Objects Frequency







1.75m long metal bar






Large piece of metal falls off one lift onto another





ID plate imbedded in deck





Large, 1.8kg, spanner

9





350g Wheel key










Pinch bar left on lift





7kg steel plate








Steel wire reel








Potential / Dropped Objects Breakdown



*Figures are based on incident reports 2011-2016YTD

Vessel Operators






Offshore Onshore Vessel

Logistics Providers





CAUSES



- Checks failed
- Checked several hours prior to backload
- Checks were not stringent enough
- Not ours/didn't come from here
- Inconclusive
- No response

CORRECTIVE ACTIONS

- Nothing
- Training
- TOFS
- Modification of unit or innovation
- Change to checklist





- Is cargo being lifted to vessels given the same level of scrutiny as lifts across your assets?
- Are those doing the checks fully aware of the potential of these items?
- Are they given sufficient time to conduct the checks?
- When you experience these incidents/near misses is your follow up robust enough to prevent re-occurrence?



LEADERS IN GLOBAL OFFSHORE MARINE SERVICES GULFMARK.COM