

NO FINGER POINTING !




ABERDEEN DRILLING CONSULTANTS

SHARE AND SHARE ALIKE

# TUBULAR HANDLING FINDINGS

IADC Alert 15-10 Fatality on Drill Floor



# TUBULAR HANDLING FINDINGS



## Visual Back Up

Most rigs use a system of visual back up or CCTV system.

## Finding

From the roughneck position outside of the Red zone, it was not possible to see the position of the fingers on areas of the fingerboards.

More than one occasion.



SOME TIMES THE SIMPLEST THINGS WORK BEST

