

DROPS and Bow Ties



operational excellence risk management


enables effective identification, prioritization, and reduction of risk



Focus on preventing high—consequence incidents and impacts by understanding and mitigating risks and maintaining and assuring safeguards



operational excellence management system



Risk profile

Establish risk profile for operations

Safeguard Evaluations

- Develop Bow Tie models based on identified high risks
- Assess identified safeguards for completeness and effectiveness (hierarchy of controls, human and hardware)

Assurance

- Develop assurance activities for each safeguard
- Test the assurance, how do you KNOW safeguards will function as designed?



safeguards

Definition: Safeguards are the hardware and human actions designed to directly prevent or mitigate an incident or impact.

Common safeguards include facility design elements, mechanical devices, engineered systems, protective equipment and execution of procedures.

Critical aspects of managing safeguards: establishing safeguards and sustaining and assuring safeguards


simplified bow tie model





simplified bow tie development


visualization of safeguards managing risk






completed bow tie

Static Dropped Object



assurance

- Assurance process verifies that safeguards are functioning as intended
- To sustain effective safeguards, we must analyze and act on safeguard performance data, identified through assurance activities, such as inspection, testing and audits







adding verification of safeguards

Safeguard

Periodic inspection of

per DROPS plan

primary securement as

Fitment and inspection of secondary retention

Using tied off tethered tools

Use of tools at height register

ERP, rescue teams and equipment available on site

> Established and enforced red zone

Assurance

Complete Level 1 inspection as per DROPS Plan table 2.0. Test primary securement per requirement. Identify action items.

Complete Level 1 inspection as per DROPS Plan table 2.0. Visually inspect secondary retention devices are in place and in good condition

Refer DROPS Plan section 4.8 Tools at Height. Inspect tools at height and tethers, discuss with crews to confirm use of tethered tools at height.

Refer DROPS Plan section 6.3 Tools at Height Register. Complete tools at height register for all items taken aloft and returned.

1. Updated ERP available on site. 2. Rescue teams training completed. 3. Availability of medical equipment 4. Conduct rescue with medical response drills

Refer DROPS Plan section 9.2 Exclusion zones. Visually confirm Red zone established on rig floor, markings are in good condition. Entry conditions are established and known by crew. Discuss with crews.

Verification

Verify Level 1 inspection completed as per DROPS Plan table 2.0. Verify all actions closed.

Verify Level 1 inspection completed as per DROPS Plan table 2.0. Verify all actions closed.

Verify Tools at Height availability on location. Discuss use with crews.

Review Tools at Height register for completeness. Discuss with crews

1. Review ERP. 2. Confirm rescue teams are knowledgeable on rescue techniques. 3. Confirm availability of medical equipment 4. Confirm rescue team has conducted rescue/medical drills

Review DROPS Plan section 9.2 and verify zone on rig floor is in compliance. Discuss enforcement with crews.



safeguard health

verification of safeguards

Safeguard visualization chart (with traffic lights)

	Facility A Risk Profile	Prevention													Mitigation												
#	Scenario	Consequence Category	Consequence	Risk Profile RR	Design	Flame Arrestor	Flow Restriction	Mechanical Device- Prevention	Safety Instrumented System-Prevention	lce	Process Control and Alarm	Integrity	Collision/Impact Prevention	Lifting Equipment	Weather and Natural Events Protection	Human	Other-Prevention	Containment	Overflow	Passive Fire Protection	Safety Instrumented Systems-Recovery	ļ	ire Protection	Ignition Control	Emeregency Management	Human	Other-Mitigation
1	Potential large release of oil from pipeline 1 to City X, resulting in potential personnel and public impact	PH&S	1	4							0																
2	Potential large release of ammonia from storage area, resulting in potential personnel and public impact	PH&S	1	5																							
3	Potential large release of flammable gas from Area 1, resulting in potential personnel impact	WH&S	2	4						•	0										•						
4	Potential large release of H2S from Area 2, resulting in potential personnel impact	WH&S	2	5						•	0																
5	Potential large release of LPG from storage area, resulting in potential personnel impact	WH&S	2	6																	•		•		•		

safeguard meter

Measure of safeguard functionality and status of verifications (established through assurance)

In place but is not verified to fully meet defined criteria



In place and verified to meet defined criteria

Not in place, or does not meet defined criteria



uses of bow tie models


- Fit for purpose, can be scaled to suit depending upon event used
- Can be developed in the field through facilitated learning team workshops
- Crews can visualize how and where the safeguards work
- Found the bow ties to be a good reference during job planning
- Tool for assurance teams to understand what safeguards should be in place and how to verify them
- Post investigation QA tool

simplified bow tie model






evaluate bow tie based on investigation or learning teams findings






remove causes and consequences not involved in the event





© 2018 Chevron

identify safeguards that worked and did not work





the journey and continuous improvement







thank you



