


Dropped Objects – January to June 2009

Donald Dobson

HSE




Dropped objects – monthly totals




All Incidents












Derrick & Well Ops Incidents



- Pivot pin c/w bolt and locking wire fell from upper racking arm 26m to rig floor
- Clamp retaining safety mesh to derrick beam fell to rig floor (corroded bolt)
- Lifting joint of 2-7/8" tubing, elevators slipped off, joint fell across rig floor
- Rope access radio harness clip failed, radio fell to rig floor
- Changing tugger wire, snake opened at sheave & both wires fell to rig floor
- Iron roughneck hoses caught on rig floor hatch cover which fell to moon-pool












- Whip line motor failed; load dropped 18"; headache ball fell 30ft
- Lowering scaffolding through hatch;
 board came free and fell 7m
- Floodlight dislodged from its mounting by crane and fell to deck
- Length of chain fell off bundle of pipe being lifted from supply vessel landing on walkway











- Flashing from shaker house roof blown off in high wind
- Lid from empty crate dislodged from helideck by downdraft; fell 20ft to walkway below
- Technician dropped filter housing which fell through handrail and 5m to process deck below