



# Prevention of Dropped Objects

Lenny West Onshore HSEA



## Hammer Test

- Yearly Planned Inspections
- Conducted over last 4 years (Same Areas)
- Different Teams
- What different eyes see!















Left on beam by RAT













**Tool fell approx 40 metre**





Socket torque bar 0.7kg



Type of karabiner used

NB: No locking device



Type of fixing used on original bar.

## Correct Karabiner c/w locking device



Similar Tool (Socket breaker bar)



Lockable Karabiner lanyard





# Any Questions