



DROPS Forum, Stavanger

03 June 2010

Backloaded container from North Sea Installation



Dropped Objects

Highland Prince - Wooden spar drops from top of container – 20 Mtrs above Deck



Dropped Objects

Highland Courage 1) Loose pipe / valve combination lying on bottom of tank skid.



Dropped Objects

2) Valve removed (will be stored off lift) Note: Glove in background gives scale of object



Dropped Objects

- The crane driver was asked if he was missing any of his red lights, and he replied that the top one was out!



Dropped Objects



- Highland Citadel -Telescope found on top of empty waste oil tank



Dropped Objects



Dropped Objects



Dropped Objects



M V Portosalvo - Headache ball 165 Kg - detached and entering the sea.



Dropped Objects



Door swung open on tool container the first lift they took off.

Dropped Objects



The piece of wood is a cover off a crate with approx dimensions 80cm x 60 cm x 7mm thick.

Dropped Objects




Crane operator noticed what looked to be a loose section of packing case wood on top of the crate. Once outside the 500m zone inspection showed it to be a section of packing case timber approx. 25mm x 75mm x 700mm long with six exposed nail ends some 40mm long.

Dropped Objects



The crane was lifting a heavy lift - 12.7 tonnes from our deck, on the way up he bumped into our outer rail, on port aft, so it broke. The ship was pitching/heaving due to some swell, but within working limits, The crane operator had miscalculated the distance of the lift & and movement of the ship.

Dropped Objects



Small shackle dropped from crane

Rig later confirmed that the shackle came from one of the small floodlights on the boom



DROPS Forum

06 April 2010